


Vx7
4130.160


Vx7 High Vibration Mount - 4330.237



PD10 Mast Top Bracket Assembly - 4330.301
PD10 Laser Mount Assembly LDx8 - 4320.301
PD10 L-Bar for Laser Sensor LDx8 - 4320.302
PD10 Angle Mount for Laser Sensor LDx8 - 4320.303
LDx8 Vibration Pad - 4320.304

PD10 Laser Target LDx8 - 4320.300
PD10 Laser Target Reflective Tape - 4320.299







Vx7 Cable, 14m
4230.161

CAN Terminator
(Female)
4290.813

LDx8 Laser
4120.125



Sensor PD10 Mount
4320.217



CAN Cable, 10m
4220.075




Cellular MAG Base
w/antenna 4140.030




MC-8-10 Serial 1
Cable
4230.500

CAN Cable, 10m
4220.075



IMU Sensor
4120.112

MC-8/10 Power Cable
4210.500




MC-8/10
4110.100 / 4110.101

MC-8/10 CAN 1/2
4220.501

Ignition

7.5A Fuse Link

PD10 Harness
4290.110



CAN Cable,3.5m
4220.070



12 to 24 VDC
Up Converter